Weathertzetton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0963/1

Work Order Type: Weatherization

Audit Name: 17017UC-0963

CLIENT INFORMATION

Client ID: 17017UC-0963

AGENCY INFORMATION

Agency:Upper Cumberland H R AAgency Phone:(931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact:Carlisle, RonWork Phone:Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

HOME BUILT IN 1945 1131 SQ. FT

Measures

Measure 1 Inst	all Kitchen Exhaust Far	1		Componen	its			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Kitchen exhaust fan w/ damper	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
REF	n Replacement 186 FT T PLACEMENT	RIM		Componen	ıts			Inspected
		RIM		Componen Estimated			Actual	Inspected
REF		RIM	Qty	-		Qty		Inspected
REF Comment	PLACEMENT		Qty 12	Estimated	ı	Qty	Actual	
REF Comment # Material / Labor	PLACEMENT Description / Comment Replace or Repair Trim	Units	_	Estimated	ı	Qty	Actual	
REF Comment # Material / Labor Windows	PLACEMENT Description / Comment Replace or Repair Trim	Units	_	Estimated	ı	Qty	Actual	
REF Comment # Material / Labor Windows	PLACEMENT Description / Comment Replace or Repair Trim	Units	_	Estimated	ı	Qty	Actual	
REF Comment # Material / Labor Windows	PLACEMENT Description / Comment Replace or Repair Trim	Units Each	12	Estimated	ı		Actual	

	Measure 3 Wal	l Repair 80 SQ. FT.			Componer	nts			Inspected
C	Comment AUDITO	OR STATED THAT THE H	HVAC CLO	DSET I	NEED TO B	E CLOSE	D IN.		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
2	Miscellaneous Supplies	Paneling / 32sqft	SqFt	80					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
[Field Notes:								
	Comment ATTIC A	tration Redctn ACCESS DOOR W/ R-30 100 LINEAR FOOT FOR AND CAULK 4 WINDOW	SEALING	HERST	CKS IN WA	LLS TRIN	И ETC.		Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
(Other Detail								
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:								

Measure 5 DW	/H Tank Insulation			Componen	its			Inspecte
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equipment	DHW Tank Insulation	Each	1					
	R-10 minimum-use bubble wrap							
2 Labor	DHW Tank Insulation	Each	1					
Other Detail						,		
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
	ic Ins. R-38			Componen	ots A1			Inspecte
Measure 6 Atti	ic Ins. R-38			Componen Estimated			Actual	Inspecte
Measure 6 Atti	ic Ins. R-38 Description / Comment	Units	Qty	-		Qty		Inspecte
Measure 6 Atti Comment # Material / Labor		<i>Units</i> SqFt		Estimated	<u> </u>	Qty	Actual	
Measure 6 Atti	Description / Comment Attic Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown		Qty 1131	Estimated	<u> </u>		Actual	
Measure 6 Atti Comment # Material / Labor 1 Insulation Other Detail	Description / Comment Attic Insulation - Blown		Qty 1131	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown		Qty 1131	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 7 Wall Comment	Insulation		(Compone	nts E1,N1	,S1,W	1	Inspected
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1088					
Other Detail						_		
			Measure	Sub Total:] .	Sub Total:	
Measure 8 Pres Comment	sureRelief Piping Need	led	(Compone	nts			Inspected
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Extend T/P Valve to Floor	Each	1					
2 Labor	Labor	Hour	0					
Other Detail								
			Measure	Sub Total:] ,	Sub Total:	
Field Notes:							-	
		Work O	rder Gran	nd Total:		Gran	d Total:	